

Belzona coating a acid drain with 4311

ID: 9389

Industry: *Not Specified*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: *Belzona 4311 (Magma CR1)*

Customer Location: *Oklahoma*
Application Date: *December 2023*

Problem

The customer was getting chemical attack on the concrete



Small chemical drain being coated first coat with Belzona 4311



First coat of Belzona 4311



Second and final coat of Belzona 4311.



Second drain, application with Belzona 4311

Application Situation

This job was done at a pharmaceutical company and being such the job had to be done on a weekend behind seals doors for the dust.

Application Method

This entire job was done by hand tools.

Belzona Facts

Belzona is widely used in this facility and they trust the chemical resistance from Belzona 4311

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve