

Belzona replaced the old damaged rubber protection.

ID: 9417

Industry: *Power*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Carbon steel*
Products: *Belzona 4311 (Magma CR1)*

Customer Location: *Kosice Slovakia*
Application Date: *August 2023*

Problem

Damaged rubber coating



Damaged rubber protection.



Removing the rubber surface.



The surface is ready for the application of Belzona products.



Belzona 4311 product application.

Application Situation

The repair of 55m² took 5 days, of which the most time was taken by chopping off the old rubber.

Application Method

After removing the old damaged rubber, 2 layers of paint were applied.

Belzona Facts

The application of Belzona protective coating is a more cost effective and more accessible way to repair damaged rubberization at this time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2025