

Sealing of gas pipe expansion joints.

ID: 9418

Industry: Steel & Metal Processing

Application: GSS-Gaskets, Seals and Shims

Substrate: Stainless-steel

Products: Belzona 2311 (SR Elastomer), Belzona 7311

Customer Location: Kosice Slovakia

Application Date: August 2023

Problem


At the pipe/expansion joint, due to expansion and weather conditions, the expansion jointer was torn off locally and a subsequent leak occurred.



The expansion jointer was torn off locally and a subsequent leak occurred.



Belzona 2311 was pressed into the leaks



Preparation for application of Belzona 9341 product.



The damaged compensator was finally repaired with the product Belzona 7311.

Application Situation

The only alternative to repairing the expansion joints was to replace them, which is very demanding from a technical and time point of view, due to the dismantling of the pipe above the expansion joint, the dismantling of the compensator itself, the welding of a new one and the subsequent assembly of the disassembled pipe. All using cranes.

Application Method

The surface of the pipeline and compensator was cleaned and roughened by blasting (during the shutdown of the degassed pipe). Belzona 2311 was pressed into the leaks, which was then covered with Belzona 7311 with reinforcement sheet.

Belzona Facts

Using Belzona products to repair compensator damage resulted in a quick and inexpensive solution compared to replacing the damaged parts.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve