

BELZONA STEP NOSING REPAIR


ID: 942

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: Belzona® 4111 (Magma Quartz)<div>Belzona® 4411 (Granogrip)</div>

Customer Location: Racecourse, Liverpool, England
Application Date: March 2007

Problem

Porters had been bouncing beer barrels down the steps from the bar situated on the floor above. This was damaging the concrete step nosings.



Photograph Descriptions

* Steps showing signs of damage , * Close up of damage , * Steps repaired , * Close up of repair ,

Application Situation

Damaged step nosings.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -8.

Belzona Facts

Belzona was chosen due to its high bond strength, impact resistance and hard wearing non-slip surface proven in similar environments.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve