

# BELZONA WEATHERPROOFS BALCONY

ID: 943

**Industry:** Buildings & Structures  
**Application:** RPA-Roof Problem Areas  
**Substrate:** Asphalt, Concrete, PVC  
**Products:** \* Belzona 3131 (WG Membrane) ,  
\* Belzona 9231 (Surefoot Aggregate) ,

**Customer Location:** Housing Association, Merseyside, UK  
**Application Date:** February 2007

## Problem

Water was finding its way into the flats from the balconies. Customer needed a weatherproof and non-slip solution.



## Photograph Descriptions

- \* 1. One of the three blocks of flat ,
- \* 2. Loose asphalt being removed ,
- \* 3. Belzona 3131 being applied ,
- \* 4. Aggregate being scattered onto top coat of Belzona 3131 ,

## Application Situation

Asphalt access balconies on multi-story flats.

## Application Method

Application was carried out in accordance with Belzona system Leaflets RPA-6 & 9. Loose asphalt was removed leaving either well bonded asphalt or concrete onto which a fully reinforced Belzona 3131 system was applied. An additional coat of Belzona 3131 was applied, blinded with Aggregate.

## Belzona Facts

Belzona was chosen due to its cost effectiveness, ease of application and the fact that it could be applied during winter weather

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

conditions. Use of aggregate in a top coat of Belzona 3131 creates a trafficable water and weatherproof system ideally suited to the environment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

