

BELZONA WEATHERPROOFS BALCONY

ID: 943

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Asphalt, Concrete, PVC
Products: * Belzona 3131 (WG Membrane) ,
* Belzona 9231 (Surefoot Aggregate) ,

Customer Location: Housing Association, Merseyside, UK
Application Date: February 2007

Problem

Water was finding its way into the flats from the balconies. Customer needed a weatherproof and non-slip solution.



Photograph Descriptions

- * 1. One of the three blocks of flat ,
- * 2. Loose asphalt being removed ,
- * 3. Belzona 3131 being applied ,
- * 4. Aggregate being scattered onto top coat of Belzona 3131 ,

Application Situation

Asphalt access balconies on multi-story flats.

Application Method

Application was carried out in accordance with Belzona system Leaflets RPA-6 & 9. Loose asphalt was removed leaving either well bonded asphalt or concrete onto which a fully reinforced Belzona 3131 system was applied. An additional coat of Belzona 3131 was applied, blinded with Aggregate.

Belzona Facts

Belzona was chosen due to its cost effectiveness, ease of application and the fact that it could be applied during winter weather

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

conditions. Use of aggregate in a top coat of Belzona 3131 creates a trafficable water and weatherproof system ideally suited to the environment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

