

BELZONA WEATHERPOOFS POROUS STONework

ID: 944

Industry: *Buildings & Structures*
Application: *WPA-Wall Problem Areas*
Substrate: *Sandstone*
Products: ** Belzona® 5122 (Clear Cladding Concentrate),*

Customer Location: *Private House, Manchester, England*
Application Date: *August 2007*

Problem

House had been recently renovated and sand blasted externally. This process removed the weatherproofing properties of the stonework and as a result moisture was penetrating into the house.



Photograph Descriptions

- * View of property ,
- * Windows masked up and ready to go ,
- * Applying Belzona® 5122 with spray unit ,
- * Application close up ,

Application Situation

House constructed of stone.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-8.

Belzona Facts

Customer did not want a sheen left on the building once coated. Material of choice also had to be microporous.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

