

# BELZONA WEATHERPOOFS POROUS STONework

ID: 944

Industry: *Buildings & Structures*  
Application: *WPA-Wall Problem Areas*  
Substrate: *Sandstone*  
Products: *\* Belzona® 5122 (Clear Cladding Concentrate),*

Customer Location: *Private House, Manchester, England*  
Application Date: *August 2007*

## Problem

*House had been recently renovated and sand blasted externally. This process removed the wetherproofing properties of the stonework and as a result moisture was penetrating into the house.*



## Photograph Descriptions

- \* View of property ,
- \* Windows masked up and ready to go ,
- \* Applying Belzona® 5122 with spray unit ,
- \* Application close up ,

## Application Situation

House constructed of stone.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-8.

## Belzona Facts

Customer did not want a sheen left on the building once coated. Material of choice also had to be microporous.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

