

BELZONA PROVIDES LONG TERM PROTECTION AGAINST UNDER FLOOR CORROSION

ID: 945

Industry: Chemical & Petrochemical Customer Location: Petrochemical Plant - UK

Application: GSS-Gaskets, Seals and Shims Application Date: May 2005

Substrate: Carbon Steel, Ashphalt & Concrete

Products: * Belzona 3111 (Flexible Membrane System),

Problem

As a result of water ingress through the mastic type seal, under floor corrosion had occurred to an extent that the floor needed replacing. The customer was looking for a longer lasting, more effective base seal to satisfy government agency requirements.









Photograph Descriptions

- * Before application of the Belzona system after new floor fitted,
- * Application in progress,
- * Application complete,
- * Completed application over 2 years later,

Application Situation

Carbon steel Paraxylene storage tank.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-3

Belzona Facts

This company chose to apply the Belzona system to this tank because it demonstrated their determination to increase the life of their asset. As a result of the success of this tank base seal this company has applied the system to a further 16 tanks to date. The company has also now specified the system for all tanks on-site with a further 6 already scheduled for completion. Furthermore the

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

engineer on-site has also provided us with a testimonial letter stating their satisfaction with the system.	
For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com	_