

Belzona 1818/1321 on paper mill pump

ID: 9468

Industry: *Pulp & Paper*
Application: *CEP-Centrifugal Pumps*
Substrate: *Other*
Products: *Belzona 1321 (Ceramic S-Metal), Belzona 1818*

Customer Location: *OKC*
Application Date: *July 2024*

Problem

Paper mill pump had severe wash out of years of use and needed to be repaired



Damaged pump.

Pump rebuilt with Belzona 1818.

First coating of Belzona 1321.

Finished application.

Application Situation

The pump was blasted and cleaned. After cleaning it was rebuilt with Belzona 1818. First coat of Belzona 1321 was applied and shortly after that second coat of Belzona 1321.

Application Method

The application was completed according to the corresponding Instructions for Use.

Belzona Facts

Belzona has repaired a lot of pumps for this client they were trusted to have this pump done quickly and within budget.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve