

# **Parking Garage Expansion Joints**

ID: 9487

Industry: Buildings & Structures Customer Location: Knoxville Tennessee

Application: GSS-Gaskets, Seals and Shims Application Date: May 2023

Substrate: Concrete

Products: Belzona 4521 (Magma-Flex Fluid), Belzona 4911 (Magma TX Conditioner)

#### Problem

The expansion joints were leaking water into storage rooms underneath the parking garage when it rained.







Close-up of the expansion joint Finished application. needing repair.

This is a pic of before the work was done.

### **Application Situation**

By using Belzona, the expansion joints will last longer than ordinary joint filler. Also, the items stored in the storage rooms underneath the expansion joints will not have water damage.

## **Application Method**

The old material in the expansion joints were removed. Then the joints were taped off. Then new backer-rod was placed in the joints. Then the conditioner (Belzona 4911) was applied. Then the Belzona filler (4521) was applied to fill the joints.

### **Belzona Facts**

Belzona was chosen because of the relationship the Director of Engineering had with the Belzona rep. He had confidence in the material and the voice of the rep.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve