

# Repair of PVC pipe with leak from failed fiber glass installation

ID: 9493

Industry: *Steel & Metal Processing*

Customer Location: *Hamilton, Ontario*

Application: *VPF-Valves, Pipes and Fittings*

Application Date: *July 2024*

Substrate: *PVC*

Products: *Belzona 1212, Belzona 1982 (SuperWrap II), Belzona SuperWrap, Belzona 9111 (Cleaner Degreaser)*

## Problem


*Major leaks was experienced from a failed fiber glass installed earlier by customer to fix problem.*



Failed fiber glass



Newly installed Belzona Superwrap II



Belzona Super wrap installed successfully.

## Application Situation

Customer was relying not only on the performance of Belzona Super wrap II but also on the quick turn around of our range of solutions.

## Application Method

The failed fiber glass was abraded with the aid of a power tool after which the surface was wiped clean using the cleaner/ degreaser Belzona 9111. After drying, Belzona 1212 was mixed and apply with Belzona Super wrap installed afterwards.

## Belzona Facts

Belzona was not only able to seal the leak in a couple of minutes but also completed the whole installation and the equipment put back in service as stipulated in the product IFU. Follow up with customer confirmed that there was no leak or sipping as the Super wrap II successfully solve the issue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

