

Belzona floor repair

ID: 9517

Industry: *Food & Drink*

Customer Location: *Oklahoma*

Application: *FPA-Floor Problem Areas*



Application Date: *February 2024*

Substrate: *Concrete*

Products: *Belzona 4111 (Magma-Quartz), Belzona 5811 (Immersion Grade)*

Problem

This floor was extremely slippery and was worn down form years of use



The floor was prepped with hand tools, cleaned and then repaired whit Belzona 4111.

First coat of Belzona 5811 black on floor for protection

Second and final coat of Belzona 5811

The floor 2 weeks after Application

Application Situation

When the floor was done, the floor was grinded and cleaned by hand and then rollers and brushes were used to apply the Belzona product to the floor.

Application Method

4inch grinders
epoxy rollers
brushes
acetone
type and buckets

Belzona Facts

This customer has used Belzona 5811 and 4111 for years. All of the applications that has been done is still in service

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve