

BELZONA EMERGENCY RECLAMATION OF A REFINER

ID: 953

Industry: Pulp & Paper

Application: PDP-Positive Displacement Pumps

Customer Location: Paper mill, United Kingdom

Application Date: August 2000.

Substrate: Cast Iron

Products: Belzona® 1311 (Ceramic R Metal)<div>Belzona® 1321 (Ceramic S Metal)</div></div>

Problem

Severe erosion in the refiner body and the end cover/door led to several holes necessitating repair



Photograph Descriptions

* Refiner case prior to the application in 2000 , * The August 2000 rebuild and coating , * After seven years and one intermediate coating, still in excellent condition. The repair area was between the top two bolt holes , * Close-up after application of another coat of Belzona® 1321 ,

Application Situation

Disc refiner

Application Method

The original application was carried out in accordance with Belzona Know-How System Leaflet PDP-6.

Belzona Facts

In 2004 the refiner was inspected and a further coat of Belzona® 1321 was applied. Now in December 2007 it has been checked again and found still to be in excellent condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve