

Belzona repairs forklift leak

ID: 9558

Industry: *Pulp & Paper*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Carbon steel*
Products: *Belzona 1212*

Customer Location: *Castlegar*
Application Date: *September 2024*

Problem

Leak in hydraulic tank of forklift



Prepared area



Repaired area

Application Situation

Leak in forklift hydraulic tank, could not use the equipment

Application Method

Area prepped by hand tools and repaired with belzona 1212 and 9341

Belzona Facts

Repair was completed in 3 hours from initial contact. Saved valuable downtime of important equipment

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve