

# Belzona repairs forklift leak

ID: 9558

Industry: *Pulp & Paper*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Carbon steel*  
Products: *Belzona 1212*

Customer Location: *Castlegar*  
Application Date: *September 2024*

## Problem

*Leak in hydraulic tank of forklift*



Prepared area

Repaired area

## Application Situation

Leak in forklift hydraulic tank, could not use the equipment

## Application Method

Area prepped by hand tools and repaired with belzona 1212 and 9341

## Belzona Facts

Repair was completed in 3 hours from initial contact. Saved valuable downtime of important equipment

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve