

# Plate patch on chip chute

ID: 9567

Industry: *Pulp & Paper*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Carbon steel*  
Products: *Belzona 1212*

Customer Location: *Castlegar*  
Application Date: *September 2024*

## Problem

*Hole found in chip chute, causing a mess of material on the floor.*



Hole prepared for repair.



Belzona 1212 used to bond plate.

## Application Situation

Client required immediate assistance with a home in a chip chute. Using belzona fast curing composites we were able to get them back up and running in as little as 4 hours.

## Application Method

Area cleaned and degreased. Surfaces hand tool prepared, cloth and metal patch used with Belzona 1212 for long term protection.

## Belzona Facts

Fast curing times allowed the client to get operational as soon as 4 hours and back in production

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve