

Local Firehall



ID: 9590

Industry: *Buildings & Structures*
Application: *WPA-Wall Problem Areas*
Substrate: *Concrete*
Products: *Belzona 4111 (Magma-Quartz)*

Customer Location: *Abbotsford BC*
Application Date: *June 2022*

Problem

Rebar was being attacked by moisture and causing it to spall.



Before repainting the firehall the customer needed to make sure that the walls were repaired.

All loose areas were removed.

After patching the area using Belzona 4111 magma quartz an angle grinder and sanding disc were used to achieve smoothness and a good transition between the old and new coating.

Once smoothed out, the area was left for the painting crew to repaint.

Application Situation

Concrete would have taken longer to cure and not offered the same properties as Belzona 4111.

Application Method

Angle grinder, trowels and sanding discs were used to prep and apply

Belzona Facts

Belzona was able to do this repair faster and use a more reliable product than any of the other options.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve