

Belzona repairs expansion joint leak

ID: 9592

Industry: *Steel & Metal Processing*

Customer Location: *Trail*

Application: *VPF-Valves, Pipes and Fittings*

Application Date: *May 2024*

Substrate: *Stainless-steel*

Products: *Belzona 2311 (SR Elastomer), Belzona 2911 (Elastomer QD Conditioner)*

Problem

Holes in an acid tank expansion joint needed to be repaired without welding.



Holes found



Preparation completed



Belzona elastomer and cloth applied



The bespoke application crew!

Application Situation

Emergency repair on exp joint was required without welding. Belzona and quick curing elastomers were used safely and successfully.

Application Method

Area cleaned and neutralized, conditioner applied followed by elastomer with reinforcement cloth.

Belzona Facts

Without the ability to weld belzona was the only option. Quick application made for short work and back in operation quickly.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve