

Repair of the dump body.

ID: 9598

Industry: *Cement*

Customer Location: *Slovakia*

Application: *SHM-Solids Handling Machinery*

Application Date: *February 2024*

Substrate: *Carbon steel*

Products: *Belzona 1813, Belzona 2111 (D & A Hi-Build Elastomer), Belzona 2911 (Elastomer QD Conditioner)*

Problem

Strong abrasion caused damage to the surface of the dump.



The missing original material was filled with the Belzona 1813 product.

Belzona 2111 product application.

Belzona 1813 was applied at a thickness of 5 mm.

Belzona 2111 was applied at a thickness of 3 mm.

Application Situation

Strong abrasion of products for the production of building materials caused damage (loss of material) to the dump. This caused production outages and equipment breakdowns.

Application Method

Surface blasting to the required Sa2.5 standard. Degreasing. Application of Belzona 1813 to the cleaned surface of the device in a total thickness of 5 mm to level the unevenness of the internal surface. Blasting and roughening of the surface. Belzona 2911 conditioner application + Belzona 2111 application.

Belzona Facts

Production outages and equipment breakdowns caused problems in production. By combining the Belzona 1813 and 2111 products, we have eliminated the need to repair the dump every month.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve