

Cooling Water Head Brought Back To Life With Belzona 1391T

ID: 9661

Industry: Oil & Gas
Application: HEX-Heat Exchangers
Substrate: Carbon steel
Products: Belzona 1111 (Super Metal), Belzona 1391T

Customer Location: Texas
Application Date: January 2018

Problem

Customer pulled several HEX for routine inspections and discovered bad pitting on one the Cooling Water Heads. They were in a small Pit-Stop and had 3 days to get this repaired and back in service.



Cooling Water Head Before

Cooling Water Head After

Application Situation

This was an emergency for the customer as they could not restart this unit without their cooling water HEX. We were able to load the head and take it to our shop. Blast and coat and return in 24 hours.

Application Method

We blasted and filled pitting with 1111, coated with 2 coats of 1391T.

Belzona Facts

Save the customer thousands of dollars by getting this back and not delaying the startup process.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve