

Belzona 3131 long term roof protection

ID: 9664

Industry: *Water / Wastewater*
 Application: *RPA-Roof Problem Areas*
 Substrate: *Other*
 Products: *Belzona 3131 (WG Membrane)*

Customer Location: *Scotland*
 Application Date: *July 2020*

Problem


Two large roofs were experiencing leaks due to ageing mineral felt. This was causing issues to the operations inside the buildings.



Belzona 3131 application



Application underway

Roof section after 4 years
service

Still in excellent condition

Application Situation

By using a liquid applied membrane these roof sections could be made watertight whilst minimising disruption to the operations on the treatment works.

Application Method

The roofs were first power washed, treated with fungicide. Two coats of Belzona 3131 WG Membrane were then applied.

Belzona Facts

The 3131 WG Membrane minimised the potential for weather disruptions. It also had the benefit of being applied direct to felt without the need for a conditioner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com