

# PROCESS WATER TANK LINING RESTORATION

ID: 9667

Industry: *Mining & Quarrying*

Customer Location: *Ontario*

Application: *TCC-Tanks and Chemical Containment Areas*

Application Date: *October 2024*

Substrate: *Carbon steel*

Products: *Belzona 1341 (Supermetalglide), Belzona 5111 (Ceramic Cladding), Belzona 6111 (Liquid Anode), Belzona 9111 (Cleaner Degreaser)*

## Problem

*Process water lining was experiencing corrosion due to erosion.*



Tank before refurbishment.



Lining after abrasive blasting.



Lining after two coats of Belzona 1341.



After application of external coating.

## Application Situation

Lining of process tank was experiencing deterioration due to erosion corrosion and required to be cleaned and protected from further damage.

## Application Method

The lining was cleaned to the required level of cleanliness by abrasive blasting and the external by power tool cleaning. The tank was further cleaned and degreased by using Belzona 9111. Two coats application of Belzona 1341 was applied as lining while two coats of Belzona 6111 primer and two coats of Belzona 5111 was applied as coating.

## Belzona Facts

Belzona was chosen based on previous performance on other application in the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve