

Concrete Stairs saved from further dilapidation.


ID: 9696

Industry: *Local Authorities & Municipalities*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: *Belzona 4111 (Magma-Quartz)*

Customer Location: *Ontario*
Application Date: *September 2014*

Problem

Stairs was experiencing cracks along the railing pillar and was on the verge of falling apart.



Cracks on stairs before repair.

Further cracks .

After surface preparation.

Stairs after repair.

Application Situation

Concrete stairs was on the verge of falling apart due to stress from the railings and customer wanted a fast repair that would enable the area opened to the public in the fastest way.

Application Method

The weak parts of the concrete stairs was removed and vacuumed. The areas were subsequently rebuilt with Belzona 4111.

Belzona Facts

Belzona repair was carried out and the area opened to for public use in matter of days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve