


Gaylord Opryland Expansion Joint

ID: 9699

Industry:	Buildings & Structures	Customer Location:	Nashville
Application:	FPA-Floor Problem Areas	Application Date:	June 2023
Substrate:	Masonry		
Products:	Belzona 2211 (MP Hi-Build Elastomer), Belzona 2941 (Elastomer SP-Conditioner)		

Problem

Customer had a failing expansion joint. It was also a trip hazard.



Expansion joint before application



Application of Belzona 2211



Application completed with Belzona 2211

Application Situation

Belzona was a great solution.

Application Method

Old failing joint was removed, and the joint was cleaned out. Tape was used to keep a straight line.

Belzona Facts

Customer has used Belzona in the past and trust the outcome.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

