

Gaylord Opryland Expansion Joint

ID: 9699

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Masonry*
Products: *Belzona 2211 (MP Hi-Build Elastomer), Belzona 2941 (Elastomer SP-Conditioner)*

Customer Location: *Nashville*
Application Date: *June 2023*

Problem

Customer had a failing expansion joint. It was also a trip hazard.



Expansion joint before application



Application of Belzona 2211



Application completed with Belzona 2211

Application Situation

Belzona was a great solution.

Application Method

Old failing joint was removed, and the joint was cleaned out. Tape was used to keep a straight line.

Belzona Facts

Customer has used Belzona in the past and trust the outcome.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve