

Hospital Drain

ID: 9706

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: *Belzona 4111 (Magma-Quartz), Belzona 5231 (SG Laminate)*

Customer Location: *Columbia TN*
Application Date: *August 2024*

Problem

Drain was leaking in patients room.



Drain condition before repair with Belzona



Drain condition before repair with Belzona



Final application of Belzona solution



Final application of Belzona solution

Application Situation

Customer was planning on replacing the concrete and drain before I gave them the option to repair it.

Application Method

Concrete was prepared with hand tools and cleaned before doing the repair.

Belzona Facts

Belzona was cheaper and less time consuming than to replace the old concrete and drain

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve