

Hospital Drain

ID: 9706

Industry: Buildings & Structures

Customer Location: Columbia TN

Application: FPA-Floor Problem Areas

Application Date: August 2024

Substrate: Concrete

Products: Belzona 4111 (Magma-Quartz), Belzona 5231 (SG Laminate)

Problem

Drain was leaking in patients room.



Drain condition before repair with Belzona



Drain condition before repair with Belzona



Final application of Belzona solution



Final application of Belzona solution

Application Situation

Customer was planning on replacing the concrete and drain before I gave them the option to repair it.

Application Method

Concrete was prepared with hand tools and cleaned before doing the repair.

Belzona Facts

Belzona was cheaper and less time consuming than to replace the old concrete and drain

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve