

Belzona Superwrap II Restores Fuel Storage Tank Pipeline

ID: 9767

Industry: Oil & Gas
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel
Products: Belzona 1211 (E-Metal), Belzona 1982 (SuperWrap II)

Customer Location: NSW Australia
Application Date: September 2023

Problem

Pipeline to storage tank was suffering from thin wall corrosion at the weld seam.



Pipeline to storage tank.



Surface preparation and weld seam rebuilt with Belzona 1212 E Metal



Application of Belzona 9381 Reinforcement Tape



Super Wrap II repair completed

Application Situation

This repair was completed in 2 days ensuring a quick turnaround and return to service.

Application Method

Belzona Superwrap II 10-year compliant repair installed by the onsite Rezitech Services Team

Belzona Facts

Belzona SuperWrap II is a composite repair solution designed to restore strength to weakened or holed metallic substrates.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve