

# BELZONA MEMBRANE TO THE RESCUE

ID: 979

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Felt*  
Products: *\* Belzona 3131 (WG Membrane),*

Customer Location: *Hotel, Edinburgh, Scotland*  
Application Date: *December 2007*

## Problem

*Water penetrating gutter joints due to weight of water on the joints. Owner required immediate repairs to prevent disruption to business.*



## Photograph Descriptions

- \* View of the "tired" and uncoated roof ,
- \* Area where water was penetrating ,
- \* Completed gutter, the main problem area ,
- \* Completed Belzona application ,

## Application Situation

Felt roof over hotel restaurant.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and RPA-6.

## Belzona Facts

The customer was impressed with the fact that repairs were completed without causing a major disruption or noise to restaurant

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

guests. The application was completed during the cold month of December.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

