

BELZONA MEMBRANE TO THE RESCUE

ID: 979

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Felt*
Products: ** Belzona 3131 (WG Membrane) ,*

Customer Location: *Hotel, Edinburgh, Scotland*
Application Date: *December 2007*

Problem

Water penetrating gutter joints due to weight of water on the joints. Owner required immediate repairs to prevent disruption to business.



Photograph Descriptions

- * View of the "tired" and uncoated roof ,
- * Area where water was penetrating ,
- * Completed gutter, the main problem area ,
- * Completed Belzona application ,

Application Situation

Felt roof over hotel restaurant.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and RPA-6.

Belzona Facts

The customer was impressed with the fact that repairs were completed without causing a major disruption or noise to restaurant

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

guests. The application was completed during the cold month of December.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

