

IN-SITU BELZONA REPAIR TO DRYER ROLLER

ID: 98

Industry: *Pulp & Paper*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Paper Mill in France*
Application Date: *May 1993*

Substrate: *Steel*
Products: ** Belzona® 1111 ,*

Problem

Collapse of bearing caused damage to the journal



Photograph Descriptions

- * General view of the damaged drying roller journal ,
- * Former clamped in place ,
- * Former removed showing accurately rebuilt journal ,

Application Situation

Bearing journal on dryer roller of paper machine

Application Method

Application was carried out in accordance with Belzona System Leaflet MPT-2.

Belzona Facts

This application was completed in half a day whereas traditional repair would have involved dismantling of the machine and would have taken more than two days and associated loss of production. After 5 years, repair is still in service and the customer was totally satisfied.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve