

BELZONA HOT OFF THE PRESS

ID: 980

Industry: *Pulp & Paper*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Regional Newspaper, Leeds, UK*
Application Date: *May 2007*

Substrate: *Rubber*
Products: *Belzona® 2311 (SR Elastomer)*

Problem

Large hole torn in the belt caused by a metal tool being dropped onto the belt.



Photograph Descriptions

* Damaged belt , * Preparation in progress , * Finished application, with customer admiring his work ,

Application Situation

Conveyor belt carrying rejected newspapers.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

Belzona Facts

Due to the nature of the customers business and the need for this particular belt to be running almost 24 hours a day seven days a week, it was impossible to replace the belt and would cost around £3000. Utilising the Belzona system it cost them around £40 in materials and they got the belt back up and running within 2 hours, in time for the next print run.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve