

Belzona SuperWrap II Repair & Reinforcement of Seawater Pipelines on LNG Ship

ID: 9801

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Turkey / Yalova*
Application Date: *February 2025*

Substrate: *NAB Nickel Aluminum Bronze*
Products: *Belzona 1212, Belzona 1981 (SuperWrap II)*

Problem

The CuNiFe seawater pipelines ranging between DN65 to DN300 on an LNG ship were weakened and leaking due to corrosion. Customer choose to repair the leaks and reinforce thinned pipelines with Belzona SuperWrap II.



Weakened and leaking areas in the pipelines.



The leaks were repaired by with Belzona 1212.



Belzona SuperWrap II has been applied on DN300 pipelines.



Belzona SuperWrap II has been applied on DN200 pipelines.

Application Situation

Seawater system CuNiFe pipeline of an LNG ship. Customer saved great amount of time and cost by repairing and reinforcing the pipes with Belzona SuperWrap II.

Application Method

Surface preparation was carried out by power tool cleaning SSPC-SP11. The surface was cleaned with Acetone and allowed to dry. Then, Belzona 1212 was applied to the leaking areas. After Belzona 1212 was cured, its surface was sanded down and then the Superwrap II fiber wrapping system was applied onto prepared pipe surfaces. Finally, application sections were consolidated with release film and left to cure.

Belzona Facts

The CuNiFe pipelines on the LNG ship were leaking and weakened. Since the pipe structure was CuNiFe, it was not possible to repair it by welding. The customer had to completely replace the pipelines, which would have been a significant loss of time and money. At this point, Belzona came to the rescue. Belzona repaired and reinforced the CuNiFe pipelines with the Belzona SuperWrap II wrapping system. This process was completed in a very short time compared to replacement. The customer saved significant time

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

and cost plus protected their pipelines against future corrosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

