

# Belzona Eliminates Tripping Hazards at a Medical Facility

ID: 9804

**Industry:** Buildings & Structures  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** Belzona 4131 (Magma-Screed), Belzona 4411 (Granogrip), Belzona 4911 (Magma TX Conditioner)

**Customer Location:** West Palm Beach  
**Application Date:** March 2025

## Problem


An uncomfortable step was creating serious problems on the transition from rooms to bathrooms at a healthcare facility. The patients were tripping at a serious pace. Belzona came to the rescue.



Existing transition from room to bathroom.



Removal of tripping hazard and surface preparation.



A new transition created with Belzona 4131.



Belzona 4411 applied as topcoat.

## Application Situation

The medical facility had references of similar jobs completed at other facilities and were looking for a permanent solution.

## Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-1. After removing existing tripping hazard and excavating to create a solid foundation, Belzona 4131 was used to fill the space. Then, Belzona 4411 was used to complete a smooth transition.

## Belzona Facts

Belzona products and know-how procedures have proven to perform excellently. The medical facility didn't want to keep dealing with these issues every other year. 13 transitions were created with the Belzona system for this project on first floor. There are four floors more to complete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve