BELZONA RESTORES SCHOOL TOWER

ID: 981

Industry: Application: Substrate: Products:

Buildings & Structures WPA-Wall Problem Areas Stone & Wrought Iron * Belzona® 1111 (Super Metal) , * Belzona® 4231 (E Magma Quartz) , * Belzona® 6111 (Liquid Anode) ,

* Belzona[®] 5111 (Ceramic Cladding),

* Belzona® 5122 (Clear Cladding Concentrate),

Customer Location: *Primary School, UK* Application Date: *November 2007*

Problem

Cracking and spalling of 2 stone towers and corrosion of connecting wrought iron metalwork created a Health & Safety risk.







Photograph Descriptions

- *
- * The problem ,
- * Stone removal,
- * Completed rear tower,
- * Completed work ,
- ,

Application Situation

Two stone towers connected with a wrought iron construction at the top of an old school building.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets WPA-4 & 8. The stonework was rebuilt with Belzona[®] 4231. Belzona[®] 1111 used to rebuild corrodedl wrought iron before protecting with Belzona[®] 6111/5111 system. Belzona[®]

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015Belzona products areFS 695214manufactured under an ISOISO 14001:20159000 Registered QualityEMS 695213Management System.

www.belzona.com



5122 applied to stonework for long term protection.

Belzona Facts

Using Belzona we were able to preserve the original aesthetics of the building in keep with the period build of the school! Also the cost of the job was £6,500 including labour. This gave the Council a considerable saving compared to rebuilding the towers from scratch or alternative methods of repair that wouldn't uphold the aesthetics of the building.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are FS 695214 ISO 14001:2015 EMS 695213

manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

