

# Belzona Shaft Repair on Commercial Mixer in Food Production Facility

ID: 9851

Industry: Food & Drink

Customer Location: Mississauga, Ontario

Application: MPT-Mechanical Power Transmission

Application Date: June 2025

Substrate: Carbon steel

Products: Belzona 1311 (Ceramic R-Metal), Belzona 9411 (Release Agent)

## Problem

The Client, operating a Food Production facility in Mississauga, Ontario. Had a large scale, horizontal mixer experiencing advanced wear on several output shafts. Subsequently, the mechanical seals were unable to perform due to the damage, causing both product leakage and potential contamination. The equipment was a piece of legacy hardware that had previously been retrofitted and repaired using an unknown product.



Showcasing the piece of equipment



Completed surface prep of the damaged area



Repaired area using the Forming technique



Completed repair area

## Application Situation

Upon inspection, it was determined that due to the sheer size of the mixer, its location within the facility, along with the cost associated in disassembly and transport. That they were unable to suffer the necessary downtime and sought a repair in place solution from Belzona.

## Application Method

Surface prep was completed using a combination of Sanding Strips, Grinders, and Manual Filing tools.

The area was then taped off to prevent excess product from curing on the unaffected shaft areas.

This repair was completed using a custom printed 3D mold, coated with Belzona 9411 Release Agent

The Molds were then used in conjunction with Belzona 1311 to complete the repair using the proper Forming Technique.

## Belzona Facts

Belzona saved the company countless dollars by eliminating extended downtime. The alternative would have been extremely costly due to specialized personnel needed to move and transport the damaged equipment. Plus the repair and reinstallation time. Without the need to disassemble and move the equipment, they were able to keep the rest of their production areas open and

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)



operational.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

