

# Belzona saves Chopper pumps destined for the scrapyard

ID: 9856

Industry: Water / Wastewater Customer Location: West Midlands, England

Application: CEP-Centrifugal Pumps Application Date: January 2023

Substrate: Cast Iron

Products: Belzona 1321 (Ceramic S-Metal)

#### **Problem**

The local water company have 16 Landia chopper pumping assets on the flagship Bio plant recirculating the digesters. The current annual spend on new pump wear parts are in excess of 100k per annum.

The Customer free issued new wear components consisting of Front wear plate, Back wear plate and Volute casing, Grit blasted new components to achieve correct surface profile in line with SA2.5 Applied Belzona 1321 Abrasive Resistant coating.









Wear plate being coated

Wear plate being coated

Wear plate being coated

After 6 months being in service

### **Application Situation**

The customer was saving in excess of £110k a year on parts this has now more than halved coating with Belzona

After the 6 month inspection the customer stated the following below

The service and inspection were carried out last week with success. We have saved the parts in between servicing and they will last until the next service. Doubling the life of the parts!!!

## **Application Method**

Gritblasted to SA Standard
Coated with Belzona 1321

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®

Repair • Protect • Improve

### **Belzona Facts**

The service and inspection were carried out last week with success. We have saved the parts in between servicing and they will last until the next service. Doubling the life of the parts!!!

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

www.belzona.com