

Belzona 4111 for rebuilding stairs

ID: 9857

Industry:	Commercial Facilities	Customer Location:	Dayton, OH
Application:	FPA-Floor Problem Areas	Application Date:	August 1984
Substrate:	Concrete		
Products:	Belzona 4111 (Magma-Quartz),Belzona 4911 (Magma TX Conditioner)		

Problem

The concrete on these steps was completely worn posing a dangerous work environment



Picture of the problem area



Cleaned and applying Belzona 4911 (TX-Conditioner)



Belzona 4111 (Magma Quartz) being trowel applied



Finished!

Application Situation

This facility needed safer access to various parts of their facility and replacement wasn't an option.

Application Method

The application area was mechanically ground, Belzona 4911 applied and then Belzona 4111 applied providing a long term solution.

Belzona Facts

Belzona was used in lieu of replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

