

Hi chem Pump feet protection

ID: 9897

Industry: *General Industry*
Application: *CEP-Centrifugal Pumps*
Substrate: *Carbon steel*
Products: *Belzona 4311 (Magma CR1)*

Customer Location: *Oklahoma city*
Application Date: *March 2025*

Problem

The Pump base was being eaten up by a combination of chemicals in their system in only 3 months.



Pump pedestals being blasted



Pump pedestals first coat with Belzona 4311



Pump pedestals Close up first coat



Pump pedestals second coat

Application Situation

The pump basis had to be done on-site at the customers premises.
Belzona was the only option for them.

Application Method

Blasting, hand application

Belzona Facts

The pump basis has not been for several months

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve