

BELZONA® PREVENTS LEAKAGE IN A BALL MILL BEARING JOURNAL

ID: 990

Industry: *Mining & Quarrying*

Customer Location: *Copper Mining Plant, Bulgaria*

Application: *GSS-Gaskets, Seals and Shims*

Application Date: *from June, 2007 till to May,2008*

Substrate: *Mild Steel*

Products: ** Belzona® 1321 (Ceramic S-Metal) Belzona® 1311 (Ceramic R-Metal) Belzona® 1221 (Super E-Metal) ,*

Problem

Wear on the housing due to ingress of the ore particles and water into the annular space between the insert(rubberized screw conveyor) and the housing(the journal of the mill). As a consequence a severe corrosion and abrasion occurred.



Photograph Descriptions

* Inside view of the Ball Mill Injection ports were created axial in the front of the insert with Belzona® 1221 and then Belzona® 1321 was injected to complete sealing of the annular gap Injection of Belzona® 1311 as irregular shimming along the insert length The applied Belzona materials still in perfect condition after 9 month and more than 5,500 working hours of the equipment ,

Application Situation

Ball Mills used to grind ore for copper production

Application Method

Application was carried out according modified versions of Belzona Know-How Leaflet GSS-9 and SOS-9. Belzona® 1321 was used to seal the annular gap at the inlet of the insert on the milling side and to prevent getting through of the milled particles between the insert and its housing (mill journal). Additionally approx. 2 kg of Belzona® 1311 were injected in each one of the certain locations along the insert length thus to create irregular shims and to support insert and to prevent its movement and vibrations.

Belzona Facts

Previous conventional repair by welding of the entire annular gap was not successful because of the heavy movement and vibrations so soon welds cracked. Belzona decision expanded the life of the equipment and was proven to be time and money saving. The regular inspection 9 months after completion of the first test repair with Belzona (resp. more than 5,500 working hours of the equipment) reviewed still perfect seal of the annular gap. Additionally two more mills were sealed, meantime with training of the customer maintenance staff. Since the mid of 2008 all similar repairs have been done by trained local staff.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

