

Belzona repairs Community changing room container


ID: 9920

Industry: Local Authorities & Municipalities
Application: WPA-Wall Problem Areas
Substrate: Aluminum
Products: Belzona 3121 (MR7)

Customer Location: Nottingham
Application Date: March 2025

Problem

A community Junior football team were using a modified container as their main changing and shower facility. The roof and walls were found to be letting in rain water and needed to be sealed



The container on first inspection

Showing previously failed repairs

Belzona repairs carried out by one of the client's contractors

Container walls and roof resealed with Belzona 3121

Application Situation

The community football team has limited resources and almost zero budget. The local authority stepped in to help and make good the team's facilities, preventing water ingress and giving them a useable space for changing and after-match activities

Application Method

High pressure wash all joints and remove as much of the previous failed repair as possible

Wire brush all target areas to remove any loose, rusty and dirty particles

Clean down all target area with Belzona 9111

Mix and apply 2 x coats of Belzona 3121 incorporating Belzona 9331 reinforcing sheet to all target areas on walls and roof

Belzona Facts

The only other alternative considered was to replace the container. Budgets did not allow for this so they called on Belzona, which has proved itself many times to the local authority

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve