

Belzona repairs hospital shower

ID: 9927

Industry:	Buildings & Structures	Customer Location:	Lafayette
Application:	FPA-Floor Problem Areas	Application Date:	June 2025
Substrate:	Masonry		
Products:	Belzona 5815,Belzona 9111 (Cleaner Degreaser)		

Problem
Patient rooms shower floors leaking



Shower floor before

Shower floor during surface
preparation

Shower floor after completion

Application Situation

Patient shower floor was leaking when showers were being used. This was causing ceiling tile to be wet on the floor beneath and causing bacteria and having to close patient rooms. Belzona was as ample to do two rooms and release them back in 24 hours.

Application Method

Application was prepped by angle grinder with diamond ad with dust collector. Wiped down with cleaner, degreaser. Applied two coats of Belzona 5815 according to IFU incorporating aggregate.

Belzona Facts

Belzona was able to do two different showers and release the to be used in 24 hours. The competition was say three to four days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

