

BELZONA ROOF APPLICATION STILL WATERTIGHT 20 YEARS ON


ID: 993

Industry: *Buildings & Structures*
 Application: *RPA-Roof Problem Areas*
 Substrate: *Exposed aggregate concrete*
 Products: ** Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Auto manufacturer, Wentzville, MO*
 Application Date: *October 1988*

Problem

Water was leaking in, staining wallpaper, ceiling tile and carpet causing an obvious unsightly mess.



Photograph Descriptions

- * Belzona® 3911 being applied ,
- * Belzona® 3111 application ,
- * Follow up picture February 2008 ,

Application Situation

Parapet wall joints on visitors center leaking. Previous attempts with silicone sealant failed quickly.

Application Method

Application carried out in accordance with the Belzona Know-How System Leaflet RPA-10.

Belzona Facts

Labor costs of applying silicone sealant, which did not work, far exceeded the cost of the Belzona application. 20 years later, no leaks!

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com

BELZONA®
 Repair • Protect • Improve