

BELZONA FLOOR REPAIR 24 YEARS ON

ID: 994

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4111 (Magma Quartz) ,

Customer Location: Auto manufacturer, Wentzville, MO
Application Date: Summer 1984

Problem

Rough area caused vehicles to lose their load, creating a safety hazard and damage to package contents. In addition, the rough ride damaged sensitive electronic equipment.



Photograph Descriptions

- * Original floor in 1984 ,
- * Belzona® 4111 application completed ,
- * Belzona® 4111 in February 2008 ,

Application Situation

Floor in front of highly trafficked overhead doorway leading to production area. Work had to be carefully scheduled so as not to impede constant traffic flow.

Application Method

Application was carried out in accordance with the Belzona Know-How System Leaflet FPA-1. Application was carried out in two halves so as not to disrupt constant traffic flow.

Belzona Facts

Safety concerns were paramount. One single piece of damaged electronics far surpassed the cost of the entire Belzona application. After 24 years, there is some slight damage, but the floor is still performing satisfactorily.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA®
 Repair • Protect • Improve