

# High Visibility Marking for fall Hazard

ID: 9942

Industry: Water / Wastewater

Customer Location: Victoria, BC

Application: FPA-Floor Problem Areas

Application Date: June 2025

Substrate: Composite


Products: Belzona 5231 (SG Laminate), Belzona 9231 (Surefoot Aggregate)

## Problem

The customer recognized a safety hazard atop wastewater tanks. When workers are present they must walk atop these tanks and the potential to trip and fall could result in a 4-5M fall. High visibility line markings were needed




High visibility markings identifying fall hazard



Clean lines, 3 coats total were applied



Text application using custom stencil



A total of 7 tank lids were completed

## Application Situation

Belzona BC has a long standing history of success with the plant and our products are recognized as the #1 choice for such applications.

## Application Method

The areas were masked off in neat and tidy lines and a template was made indicating 'FALL HAZARD' as specified by the safety teams. Belzona 5231 was applied by brush and roller and Belzona 9231 Surefoot Aggregate was broadcasted to rejection. A final coat of Belzona 5231 was applied as a top coat.

## Belzona Facts

Competitor high visibility products had previously been applied and lasted less than ONE year.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve