

# Belzona protects Containment Area in a Wastewater plant

ID: 9947

Industry: *Water / Wastewater*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Concrete*  
Products: *Belzona 5815*

Customer Location: *Victoria, BC*  
Application Date: *June 2025*

## Problem

*A recent leak in the containment area had water penetrating through cracks in the concrete into an electrical room below.*





Photo of containment area with storage tanks removed



Application in progress



View of containment area



Finished application

## Application Situation

A flexible coating was needed to bridge cracks and provide long term protection

## Application Method

The concrete was ground using diamond cup grinders with hepa-vac systems. Two coats of Belzona 5815 were applied by brush & roller.

## Belzona Facts

As the trusted coating supplier / contractor for the plant, Belzona was chosen from past successes in the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve