

# BELZONA KEEPS BEET SLICER RUNNING

ID: 10


Industry: Sugar  
Application: MPT-Mechanical Power Transmission

Customer Location: Sugar Beet Mill in North Dakota, U.S.A.  
Application Date: 1983

Substrate: Carbon Steel  
Products: \* Belzona® 1111 (Super Metal) ,

## Problem

Bearing failure damaged beet slicer shaft



## Photograph Descriptions

- \* View of damaged shaft . ,
- \* Application of Belzona® 1111 (Super Metal). ,
- \* Use of a former to rebuild shaft. ,
- \* Completely rebuilt shaft. ,

## Application Situation

Beet slicer shaft

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet MPT-2.

## Belzona Facts

Repair allowed customer to save time and money by avoiding disassembly of machinery.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve