

Belzona protects concrete & drainage areas

ID: 10017

Industry: Power
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: Belzona 5811 (Immersion Grade), Belzona 5831 (ST-Barrier), Belzona 9111 (Cleaner Degreaser)

Customer Location: Orapa, Botswana
Application Date: October 2025

Problem

Areas were contaminated by accidental oil and diesel spillages causing environmental complications.



Contaminated areas before cleaning commences.



Cleaning in progress. Belzona 9111 degreaser, concrete cleaner & a water based detergent were used and then high pressure washed with clean water.



Coating in progress.



Completed work!

Application Situation

As we have successfully coated a contaminated waste oil filter bund wall in 2024 for the same customer, they had no hesitation in issuing a purchase order for this repair, seeing how exceptionally Belzona products work. Our local branch had stock available, and the works were completed in three days.

Application Method

Contaminated areas were degreased with Belzona 9111 & concrete cleaner. They were then cleaned with a water based detergent and pressure washed with clean water. Belzona 5831 was used as a first coat followed by a top coat of Belzona 5811.

Belzona Facts

Belzona 5831 secured the job for its outstanding surface tolerant characteristics.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2025


BELZONA
Repair • Protect • Improve