

A GOOD NIGHT WITH BELZONA

ID: 1004

Industry: *Buildings & Structures*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Cast iron*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Local municipality, Slovenia*
Application Date: *July 2007*

Problem

Manholes on the street were causing a lot of noise due to uneven cover seat. Local people call them "Singing Covers".



Photograph Descriptions

* Manhole , * Applying Duct tape and Belzona® 9411 , * Rebuilding manhole cover seat with Belzona® 1111 , * Manhole in place and position marked ,

Application Situation

Sewage manhole on the local street.

Application Method

The manhole seats were roughened and then degreased.

Cover plate ends were protected with Duct tape and Belzona® 9411. Belzona® 1111 was used to rebuild the manhole cover seat in accordance with Belzona Know-How System Leaflet GSS-8.

Belzona Facts

Belzona® 1111 made a cost effective solution and a perfect fit of the manhole cover in its seat eliminating noise.

Conventional replacement method takes time, a lot of work and different material (asphalt, reinforced concrete). The cost savings by using Belzona technology is about 200,00 EUR per manhole.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve